1263442 - R8 SDMS

PANAFAX REQUEST

MONTANA EPA OFFICE

U.S. EPA. REGION VIII

TO: Steve Haw thorne
OFFICE: 8HWM-ER
FACSIMILE NO.: 8-330-1647
FROM: Jim Harris
OFFICE: 8MO
NUMBER OF PAGES TO FOLLOW:
REMARKS: Steve-given the available choices, of
had to mark the second one of don't
helieve that there is any need for a removal at BN-Somera-
removal at BN- somewa-

MONTANA OFFICE PANAFAX: FTS 585-5434

CONFIRMATION NUMBER: FTS 585-5486

COMMERCIAL: (406) 449-5434

CONFIRMATION: (406) 449-5486

NPL Site	Name: BN-Somers 7	TE Plant, mr	
	have completed a prelimin take the following action	ary review of the above site and (check one):	10
	A site visit needs to hassessment can be done. the visit for	We have tentatively scheduled	ą
	It is unlikely there is an ongoing removal acti	an immediate threat or there a lon to address any threats.	2.8

We believe that a removal action is varranted and are

proceeding with stiorts to institute it while the assessment form is being completed.

Osc Sate